

Hardware Connection Packing List

P3

3DMAKERPRO

- **★** @3DMakerProCares
- (ii) @official3DMakerPro
- @3DMakerPro
- https://store.3dmakerpro.com/
- service@3dmakerpro.com

JimuMeta

- **♣** @JimuMeta
- @JimuMeta
- fig. https://www.jimumeta.com/
- service@jimumeta.com

Check the **Tutorial** below to know how Mole works. https://youtu.be/EpBBW7k2zMU

Download latest JMStudio from

https://forum.jimumeta.com/home/help/download.html


Get latest Manual from

https://forum.jimumeta.com/home/help/manual.html











Plug one side of the data transmission cable (as it's showing Device Cable) into the scanner, another into the computer USB2.0 port and power adapter.






* Device Cable





Plug the device cable into the port of the scanner, make sure the red dot is lined up with the groove on the port.



The small cable on the plug can assist you to pull it out.


* Turntable Cable





The turntable can be powered up by connecting it to the computer or the power adapter with the turntable cable.

PACKING LIST



- $*\ \mathsf{Product}\ \mathsf{images}\ \mathsf{are}\ \mathsf{for}\ \mathsf{ill} \mathsf{ustrative}\ \mathsf{purposes}\ \mathsf{only}.$
- * 1234 Not included in the Standard Combo.

Operating System Requirement Minimum Intel Core i5 8th, 16GB RAM, MX250 GPU with 2GB VRAM Recommended Intel Core i7 8th, 16GB RAM, NVDIA1060 GPU with 4GB VRAM To prevent antivirus software from blocking the driver, please uninstall the antivirus software.